

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Dennis Oakley Environmental Engineer			
OGM	Steve Demczak Environmental Scientist III			

Inspection Report

Permit Number:	C0150018
Inspection Type:	PARTIAL
Inspection Date:	Friday, December 16, 2005
Start Date/Time:	12/16/2005 10:00:00 AM
End Date/Time:	12/16/2005 2:00:00 PM
Last Inspection:	Wednesday, November 09, 2005

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 20's

InspectionID Report Number: 832

Accepted by: pgrubaug 1/12/2006

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DEER CREEK MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

22,769.06 Total	Permitted	✓ Federal	Underground
84.34 Total	Disturbed	✓ State	☐ Surface
P	hase I	County	Loadout
P	hase II	✓ Fee	Processing
P	hase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- 1) During entry development if sustained quantities of groundwater are encountered which are greater than 5 gpm from a single source in an individual entry, and which continue after operational activities progress beyond the area of groundwater production, PacifiCorp must monitor these flows and notify the Division within 24 hours prior to initiation of monitoring.
- 2) Vehicle access will not be allowed in Rilda Canyon from December 1 to April 15 for construction and/or maintenance of the Rilda Canyon Surface Facilities without prior written approval from the Division. This condition is for normal working circumstances and does not apply in an emergency situation.
- 3) PacifiCorp will submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.
- -The permittee is meeting these conditions at this time.
- -Permitting Actions New Surface Facilities in Rilda Canyon awaiting Mining Plan Approval. State permit issued.
- -Violations: None

Inspector's Signature	•
-----------------------	---

Date

Tuesday, January 03, 2006

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Friday, December 16, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	~		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	~		~	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150018
Inspection Type: PARTIAL

Inspection Date: Friday, December 16, 2005 Page 3 of 3

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The mine site sediment pond contained water. There were no signs of hazardous conditions. The pond was discharging during the inspection.

4.d Hydrologic Balance: Water Monitoring

The permittee is in the process of downloading water monitoring into Division's water monitoring program.

8. Noncoal Waste

The area was clear of non coal waste material.

18. Support Facilities, Utility Installations

The permittee has finished the second break out for another air intake at the Rilda Canyon.